

OVERVIEW TOOL HOLDERS



FOR 75/4, 100 AND OLDER GENERATIONS AND OTHER MACHINES

- Tool Holders are necessary, when using magnetic drilling machines without Weldon arbor.
- The capacity of magnetic drilling machines of older generations with morse taper can be enlarged.
- The cutters can then be mounted with the Tool Holders as well as on pillar drilling machines and milling machines.
- With automatic internal cooling
- All Tool Holders are supplied in a stable plastic case.

Prod.- No.

Tool Holder AMK 2 Morse Taper 2 for cutters with Weldon shank
 Ø 7/16" - 2-3/8"
 With automatic internal cooling and nipple for coolant hose
 Suitable for all machines with drill spindle MT 2

18003

Tool Holder AMK 3 Morse Taper 3 for cutters with Weldon shank
 Ø 7/16" - 2-3/8"
 With automatic internal cooling and nipple for coolant hose
 Suitable for all machines with drill spindle MT 3

18025

Tool Holder Al 3 Morse Taper 3 for cutters strong construction
 Ø 2" - 4", with keyway
 With automatic internal cooling and nipple for coolant hose

20230

Tool Holder Al 4 Morse Taper 4 for cutters strong construction
 Ø 2" - 4", with keyway
 With automatic internal cooling and nipple for coolant hose

20240

Tool Holder Al 5 Morse Taper 5 for cutters strong construction
 Ø 2" - 4", with keyway
 With automatic internal cooling and nipple for coolant hose

20250

Quick-change Tool Holder Rota-Quick® Morse taper 2
 With automatic internal cooling and nipple for coolant hose
 Suitable for all machines with drill spindle MT 2

18650

AMK2 MT without automatic cooling

18003A

AMK3 MT without automatic cooling

18025A



Prod.-No. 18003 MT2



Prod.-No. 18025 MT3



Prod.-No. 200230/200240/200250



Prod.-No. 18650